FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Assistant Engineer) Re: G.O. Ms. 20/.70/PWD Dt.23.01.1970

Asha, KS 1 Name of the Officer Little Flower English Medium School Karuvarakundu 2 Name of the School 3 Location with Name of Education District/ Subdistrict Karuvarakundu, Wandoor Classification of Building as specified in the coumn 4 of the A- Block- GF 8 Class room fitness certificate and size A- Block -FF- 8 Class room A- Block -SF- 7 Class room B- Block- GF 6 Class room B- Block -FF- 6 Class room B- Block -SF- 6 Class room 2023-24 5 Period which the certificate is issued Nil 6 Nature of defects any Nil Foundation and basement Nil Superstructure Nil Doors and windows Wood work wrought and put up Nil Nil Roof Nil Flooring Nil Miscellaneous (cracks if any) 7 Any major defects notices which will No render the building unsafe if any manner 7 Whether maintenance work has been Yes dene properly The structure is sound to 8 Whether the structure is sound or not conduct classes under normal for conducting classes

- Note:- 1 The stability of the structure should be examined also with reference to location altitude intensity of wind expourse to flood etc.
 - 2 Any additional observation if deemed necessary for the certificate may be furnished seperately with the Certificate.

Certified that the School was inspected by me on 31.05.2023 and found fit to conduct classes for the period for the reason stated above.

Place : Karuvarakundu Date : 31.05.2023

a

b

C

d

е

f

g



Signature

weather conditions.

ASHA K.S
Pen 419126.
ASSISTANT ENGINEER
LID & E.W
Karuvarakundu G.P